


QUICK OPERATION MANUAL

Fast setting procedure for the SET POINT



NOTES

P : press the P key

To change the values or the selections, use the UP/DOWN keys

Modify procedure for the configuration parameters (menù Conf)

